



NSS Exposed for 1,920 Hours




G235
Overbend (Tool Defects)




G235
Flat w/Perf.




G235
"Flat" Field



HDG G40 + CG-AG
Overbend (Tool Defects)



HDG G40 + CG-AG
Expanded Sidewall - Edge Test



HDG G40 + CG-AG
"Flat" Field